

06 December 2016

PRODUCT DISCONTINUATION NOTICE

Effective immediately, Southco is discontinuing the following products:

<u>Item</u>	<u>Description</u>
T9-20-101-20	Roller Catch
T9-20-131-20	Bullet Catch
T9-20-401-20	Roller Catch
T9-20-501-20	Roller Catch
T9-20-801-20	Roller Catch
T9-20-901-20	Roller Catch
T9-28-132-1	Bullet Catch
T9-28-135-1	Cupboard Catch
T9-28-301-20	Roller Catch

Current demand levels for these products are unable to support the investment required to maintain the quality, service, and value required of a Southco product. You are receiving this letter because your organization has purchased one or more of these items within the last 24 months.

While there is no direct replacement for these items, the following Southco products are similar in function and application, and may serve as an alternative:

T9 Cabinet catch www.southco.com/T9
02 Magnetic catch www.southco.com/02
C3 Grabber catch www.southco.com/C3

We regret any inconvenience caused by this change, and invite you to contact your local Southco representative should you need further support transitioning to an alternate product.

Sincerely,



James Ford
Director, Product Management
Southco, Inc



PROPRIETARY ITEM - EXCEPT FOR USES EXPRESSLY GRANTED IN WRITING, INFORMATION DISCLOSED HEREON IS CONFIDENTIAL AND ALL RIGHTS, PATENT AND OTHERWISE ARE RESERVED BY SOUTHCO, INC.

BULLET CATCH

REV	DATE	DRAWN/CHKD	DESCRIPTION	ITEM	PART NUMBER	MATERIAL	COLOR
				ASSEMBLY	T9-28-132-1		
				HOUSING		NYLON	WHITE
				BULLET		ACETAL	WHITE

DATE	DRAWN	CHKD	SCALE	DRAWING NUMBER
04MAY2006	AJH	KLC	4:1	J-T9-28-132
INCHES				

ALL DIMENSIONS WITHOUT TOLERANCES ARE FOR REFERENCE ONLY.



NOTES:

- A. SPRING FORCE: 4 - 5 LBS. FULLY DEPRESSED
- B. RECOMMENDED HOLE DEPTH: .600 MINIMUM
- C. RECOMMENDED HOLE SIZE: $\phi .375 \pm .005$

OBSOLETE
 Record DWG
 SEE DWG: P2018-0678
 PER PRN: *PKC* MAT 16 2018
 Initials / Date:

